

HISTORIC AMERICAN ENGINEERING RECORD

INDEX TO PHOTOGRAPHS

MOORE HAVEN LOCK, HURRICANE GATE NO. 1
Cross-State Canal, Okeechobee Intracoastal Waterway
Moore Haven vicinity
Glades County
Florida

HAER FL-18-A

Richard T. Bryant, Photographer (FL-18-A-1-6, 15, 17, 19-27), July 2000.
Ed Zealy, Photographer (FL-18-A-7-14, 16, 18), July 2000.

INDEX TO BLACK AND WHITE PHOTOGRAPHS

FL-18-A-1	OBLIQUE VIEW OF EXTERIOR OF LOWER LOCK GATES (SOUTHERN), WITH WAREHOUSE, LOCKTENDER'S OFFICE, AND UPPER GATES (NORTHERN) IN BACKGROUND, VIEW TOWARDS NORTH
FL-18-A-2	TIMBER GUIDE WALL AT DOWNSTREAM (SOUTHEAST) CORNER OF LOCK, WITH US HIGHWAY 27 (FL 720) BRIDGE IN BACKGROUND, VIEW TOWARDS SOUTH
FL-18-A-3	OBLIQUE VIEW OF SOUTHWEST CORNER OF LOCK WALL WITH WAREHOUSE, MAINTENANCE DEPOT SLIP, AND LOCKTENDER'S OFFICE IN BACKGROUND, LOWER LOCK GATES ON RIGHT, VIEW TOWARDS NORTHWEST
FL-18-A-4	PLANAR VIEW OF SOUTHWEST CORNER OF LOCK WALL WITH LOWER LOCK GATE ON LEFT, VIEW TOWARDS WEST
FL-18-A-5	PLANAR VIEW OF SOUTHEAST CORNER OF LOCK WALL WITH LOWER LOCK GATE ON LEFT, VIEW TOWARDS EAST
FL-18-A-6	VIEW OF EXTERIOR OF EASTERN LOWER LOCK (SOUTHERN) GATE WHILE OPENING WITH SPILLWAY IN BACKGROUND, VIEW TOWARDS EAST

MOORE HAVEN LOCK, HURRICANE GATE NO. 1

HAER FL-18-A

INDEX TO PHOTOGRAPHS

(Page 2)

FL-18-A-7	OBLIQUE VIEW OF INTERIOR OF LOWER (SOUTHERN) LOCK GATES WHILE DRAINED FOR REPAIRS, US HIGHWAY 27 (FL 720) BRIDGE IN BACKGROUND, VIEW TOWARDS SOUTH-SOUTHEAST
FL-18-A-8	OBLIQUE VIEW OF INTERIOR OF LOWER (SOUTHERN) LOCK GATES WHILE DRAINED FOR REPAIRS, VIEW TOWARDS SOUTHWEST
FL-18-A-9	PLANAR VIEW OF INTERIOR OF SOUTHERNMOST SECTION OF EASTERN WALL OF LOCK, VIEW TOWARDS EAST
FL-18-A-10	PLANAR VIEW OF INTERIOR OF SOUTHERNMOST SECTION OF WESTERN WALL OF LOCK, VIEW TOWARDS WEST
FL-18-A-11	PLANAR VIEW OF INTERIOR OF CENTER SECTION OF EASTERN WALL OF LOCK, VIEW TOWARDS EAST
FL-18-A-12	PLANAR VIEW OF INTERIOR OF CENTER SECTION OF WESTERN WALL OF LOCK, WAREHOUSE IN BACKGROUND, VIEW TOWARDS WEST
FL-18-A-13	PLANAR VIEW OF INTERIOR OF NORTHERNMOST SECTION OF EASTERN WALL OF LOCK, VIEW TOWARDS EAST
FL-18-A-14	PLANAR VIEW OF INTERIOR OF NORTHERNMOST SECTION OF WESTERN WALL OF LOCK, LOCKTENDER'S OFFICE IN BACKGROUND, VIEW TOWARDS WEST
FL-18-A-15	LOWER OBLIQUE VIEW OF INTERIOR OF UPPER (NORTHERN) LOCK GATES WITH CONTROL HOUSE ON LEFT, VIEW TOWARDS NORTHWEST
FL-18-A-16	INTERIOR VIEW OF UPPER (NORTHERN) LOCK GATES WHILE DRAINED FOR REPAIRS, VIEW TOWARDS NORTH
FL-18-A-17	OBLIQUE VIEW OF INTERIOR OF UPPER (NORTHERN) LOCK GATES WITH NORTHEAST LOCK WALL ON RIGHT, VIEW TOWARDS NORTHEAST

MOORE HAVEN LOCK, HURRICANE GATE NO. 1

HAER FL-18-A

INDEX TO PHOTOGRAPHS

(Page 3)

FL-18-A-18	OBLIQUE VIEW OF INTERIOR OF UPPER (NORTHERN) LOCK GATES WHILE DRAINED FOR REPAIRS, VIEW TOWARDS NORTHEAST
FL-18-A-19	OBLIQUE VIEW OF INTERIOR OF UPPER (NORTHERN) LOCK GATES WITH LEVEE AND DAM IN BACKGROUND, VIEW TOWARDS EAST
FL-18-A-20	UPPER OBLIQUE VIEW OF INTERIOR OF UPPER (NORTHERN) LOCK GATES WITH CONTROL HOUSE ON LEFT, VIEW TOWARDS NORTHWEST
FL-18-A-21	PLANAR VIEW OF NORTHWEST LOCK WALL, NORTHWEST LOCK GATE, CLOSED, AND EAST SIDE OF CONTROL HOUSE, LOCKTENDER'S OFFICE ON LEFT, LEVEE ON RIGHT, VIEW TOWARDS WEST
FL-18-A-22	VERTICAL VIEW OF EXTERIOR OF UPPER (NORTHERN) LOCK GATES WITH CONTROL HOUSE AND WAREHOUSE IN BACKGROUND, VIEW TOWARDS SOUTHWEST
FL-18-A-23	OBLIQUE VIEW OF EXTERIOR OF UPPER (NORTHERN) GATES WITH CONTROL HOUSE IN BACKGROUND, VIEW TOWARDS SOUTHWEST
FL-18-A-24	INTERIOR DETAIL VIEW OF INSIDE OF NORTHWEST (UPPER) LOCK GATE, VIEW DOWNWARDS
FL-18-A-25	PLANAR VIEW OF NORTHWEST CORNER OF LOCK WALL, EXTERIOR OF UPPER GATES (NORTHERN) ON LEFT, BAFFLES FOR DRAINING OF LOCK ON RIGHT, LEVEE IN BACKGROUND, VIEW TOWARDS WEST
FL-18-A-26	DISTANT VIEW OF EXTERIOR OF UPPER (NORTHERN) LOCK GATES, WITH TIMBER GUIDE WALL AND CONTROL HOUSE ON RIGHT AND TIMBER PYLONS AND LEVEE ON LEFT, BAFFLES ARE IN FRONT OF GATES FOR THE DRAINING OF THE LOCK, VIEW TOWARDS SOUTH
FL-18-A-27	OBLIQUE VIEW OF TIMBER GUIDE WALL AT NORTHWEST CORNER OF LOCK, VIEW TOWARDS NORTH